

NO.	NOTES	NO.	NOTE
	FOR ACTUAL WIRING DIAGRAMS OF INDIVIDUAL UNITS, SEE:	10	FORM PAPER OUT ALAR MOUNTED ON EITHER T EXTERNAL TO THE CAE
	2883WD BASE, RECEIVING ONLY - LB4 3236 WD CABINETS - LAC 203,204,205 2874 WD ELECTRICAL SERVICE UNIT LESU 7/184	10	CONNECTIONS ARE MAD C 25 AND C 26
1	2874 WD ELECTRICAL SERVICE UNIT LESU 7/184 2882 WD KEYBOARDS - LK4, 5 2900 WD MOTOR UNITS - LMU 3, 4, 6 2864 WD PAGE TYPING UNITS - LP4, 5, 7 2880 WD PAGE TYPING UNITS - LP6, 8	Н	WHEN PAPER FEED-OUTS () CONNECTIONS A (-x) IN MOTOR PO
	LEGEND	12	ASSOCIATED APPARATU ACCESSORY COMPONEN
2	O A SELECTOR MAGNET TERMINAL BLOCK (INLESU) O B LINE TEST KEY TERMINAL BLOCK (IN LESE) O C CABINET TERMINAL BLOCK O D MOTOR CONTROL TERMINAL BLOCK (IN LESU) O E POWER TERMINAL BLOCK (IN LESU) F KEYBOARD OR REC. ONLY BASE CONNECTOR. R TYPING UNIT CONNECTOR	13	CIRCUITS SHOW A SIGNA IN BOTH KEYBOARD AN WHEN SWITCH NOT USI CONNECTIONS AND OMI ()
	O S MOTOR TERMINAL BLOCK (ON LK OR LB)	14	IF LK3 KEYBOARD LB3 TYPING UNIT IS TO BE STRAP F4 TO F7 AN BE ADDED TO ITS CON COMPLETE LINE SHUN STRAP MAY ALREADY
3	DOT DASH LINES INDICATE FILTERING SHIELDING AND SUPPRESSION NETWORKS.		
4	ALL APPARATUS IS SHOWN IN UNOPERATED OR DE - ENERGIZED POSITIONS		· · · · · · · · · · · · · · · · · · ·
5	d RESISTANCE VALUES IN OHMS (⚠) b INDUCTANCE VALUES IN MICROHENRIES (从H) c capacitance values in Microfarads (从F)		÷
6	CIRCUITS SHOW FOR .060 AMP. NEUTRAL SIGNAL LINE OPERATION FOR .020 AMP. LINE CURRENT, ADD DASHED () CONNECTIONS AND OMIT CONNECTIONS MARKED (* * * * * * * * * * * * * * * * * * *
7	USE POWER AND SIGNAL LINE SUPPRESSORS AND SYNC. OR GOV FILTER MOTOR FOR INSTALLATIONS REQUIRING MINIMUM R.E. INTERFERENCE. FOR OTHER INSTALLATIONS, OMIT SUPPRESSORS AND CONNECT INPUTS AND GOV. MOTOR, IF USED, DIRECT TO TERMINALS SHOWN.		
8	USE SYNCHRONOUS MOTOR ON REGULATED 60 ~ (±1%) A.C. POWER ONLY. GOVERNED MOTOR AND OTHER POWER CIRCUITS OPERABLE ON 50-60 ~ UNREGULATED A.C.		
9	CIRCUIT SHOWS BOTH HORIZONTAL TABULATOR AND FORM START CONTROL USED ON TYPING UNIT. WHEN ONLY ONE CONTROL IS USED, OMIT CONNECTION MARKED (— X —) AND ADD PROPER DASHED (— — —) CONNECTION IN TYPING UNIT CIRCUITS.		





A

